UNITED STATES CONSUMER PRODUCT SAFETY IMPROVEMENT ACT (CPSIA) SECTION 102

CERTIFICATE OF CONFORMITY

UNIQUE IDENTIFIER: VIRCO C0C056

PRODUCT/SERIES DESCRIPTION Virco Flip-Top Technology Tables

ITEM /SERIES: All Flip-Top Technology Table units inclusive of models

FTT2424, FTT2430, FTT2442, FTT2448, FTT2460, FTT2472,

FTT2484, FTT52448, FTT3024, FTT3030, FTT3042, FTT3048, FTT3060, FTT3072, FTT3084 and FTT53048 including the various configurations, options and finishes.

CERTIFICATION: BASED ON A REASONABLE TEST PROGRAM, THIS PRODUCT COMPLIES WITH ALL RULES, BANS, STANDARDS, OR REGULATIONS APPLICABLE TO THE PRODUCT UNDER THE CPSIA OR ANY OTHER ACT ENFORCEABLE BY THE CPSC INCLUDING (List all rules, bans, standards and applicable to the product):

- 21 C.F.R. Part 1303 (Ban of Lead-Containing Paint and Certain Consumer Products Bearing Lead-Containing Paint).

- Consumer Product Safety Improvements Act (CPSIA) Section 101 (a)(2)(B).

CERTIFICATION DATE: July 30, 2025

CERTIFIED BY:

MANUFACTURER NAME: Virco Mfg. Corporation
ADDRESS: 2027 Harpers Way
CITY STATE/PROVINCE: Torrance, California

ZIP/POSTAL CODE: 90501 COUNTRY: USA

DATE AND PLACE OF MANUFACTURE:

The following information will help you interpret the 9-digit date code on the right-hand side of Virco's UPC labels. The next two digits, which are always in the range of 01 NOTICE to 99, indicate the assembly line on which the labeled product was manufactured; 01– assembly line 1, and so on. TO PREVENT STRUCTURAL FAILURES AND POSSIBLE INJURY, FURNITURE SHOULD NOT BE USED OTHER THAN FOR ITS INTENDED PURPOSE AND The next digit, which is always in the range of 1 to 3, SHOULD BE INSPECTED REGULARLY FOR LOGSE OR MISSING SCHEWS indicates the shift during which the labeled product OR RIVETS, METAL FATIGUE, CRACKS, BROKEN WELDS, MISSING was manufactured; 1= first shift, and so on ATTACHMENTS, LOOSE STAPLES, AND GENERAL INSTABILITY. FURNITURE THAT IS DAMAGED ON APPEARS TO BE UNSTABLE SHOULD IMMEDIATELY BE REMOVED FROM SERVICE, REPORTED TO THE FACILITY The next two digits, which are always in the range of MANAGER, AND REPLACED OR REPAIRED. D1 to 31, indicate the specific day of the production month: 01= the first of the month, and so on. FOR INFORMATION ON FURNITURE MAINTENANCE, OR TO REPORT FURNITURE WHICH REQUIRES SERVICE, CALL VISCO TOLL FREE AT The next digit, which is always a letter in the 1-800-44VIRCO. REPAIRS SHOULD ONLY BE MADE USING FACTORY range of A to L, indicates the production AUTHORIZED PARTS AND METHODS. 08K03113 month; A=January, B=February, and so on. M-2945 The next two digits indicate the production BLK01-CHRM year; 00= the year 2000, 01=2001, and so on, 29459059 The first digit, which is always either 1 or 2, indicates the manufacturing site of the labeled product; 1-Virco Torrance, CA and 2-Virco Conway, AR.

TEST DATE: July 30, 2025

THIRD PARTY TEST LABORATORY: Applied Technical Services, Incorporated

ADDRESS: 1049 Triad Court

CITY STATE/PROVINCE: Marietta, Georgia

ZIP/POSTAL CODE: 30062 COUNTRY: U.S.A.

RECORDS CONTACT:

NAME: Robert Lewis, Director of Safety

and Environmental Stewardship

COMPANY: Virco Mfg. Corporation

ADDRESS: 2027 Harpers Way

CITY, STATE ZIP CODE: Torrance, California 90501

PHONE NUMBER: 800.448.4726, ext. 3580

E-MAIL ADDRESS: RobertLewis@virco.com